Recommended Product

SPA8000
FXS Gateway

Linksys

Firmware 6.1.3, Hardware 1.0.0

8 port FXS – adapter

Based on the evaluation concluded October 12[th], 2009, this product is recommended for use with innovaphone PBX solutions.

Restrictions: none

No testing against standards compliance such as product safety, network access, radiation protection, CE or any other regulatory or technical requirement has been performed. innovaphone thus assumes no responsibility for any standards compliance whatsoever regarding this product.

innovaphone AG
Sindelfingen, October 12[th] 2009

Gerd Hornig
Director Sales

Christoph Künkel
Director Product Management

innovaphone